



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)
Solovay, Ken S.) Examiner: TBA
Serial No.: 10/713,855) Group Art Unit: 3738
) Confirmation No. 1888
Filed: Nov. 14, 2003) Atty. Docket No.: GCC-106-CP1
For: Rail Stent-Graft for Repair of A.A.A.) Customer No. 35996

Mail Stop Missing Parts
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450


RESPONSE TO NOTICE TO FILE CORRECTED APPLICATION PAPERS

Sir:

In response to the Notice mailed October 18, 2004, replacement drawing sheets are attached hereto.

Respectfully submitted,

Date: Oct 22, 2004


Rick Comoglio, Reg. No. 40,963
GMP|Companies, Inc.
One East Broward Blvd., Suite 1701
Fort Lauderdale, FL 33301
(954) 745-3532

Attachments: Replacement Sheets
Copy of Notice to File Corrected Application Papers

Via
Express mail
EV304655259US
OCT 22, 2004



10-25-04

Page 1 of 1

UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE
United States Patent and Trademark Office
Address: COMMISSIONER FOR PATENTS
P.O. Box 1450
Alexandria, Virginia 22313-1450
www.uspto.gov

1FW

APPLICATION NUMBER	FILING OR 371 (c) DATE	FIRST NAMED APPLICANT	ATTORNEY DOCKET NUMBER
10/713,855	11/14/2003	Kenneth S. Solovay	GCC-106-CPI

35996
GMP COMPANIES, INC.
ONE EAST BROWARD BLVD.
SUITE 1701
FORT LAUDERDALE, FL 33301

RECEIVED

OCT 21 2004

GMP Companies, Inc.

CONFIRMATION NO. 1888

FORMALITIES LETTER



OC000000014120394

Date Mailed: 10/18/2004

NOTICE TO FILE CORRECTED APPLICATION PAPERS

Filing Date Granted

DOCKETED:

OCT 21 2004

BY:

An application number and filing date have been accorded to this application. The application is informal since it does not comply with the regulations for the reason(s) indicated below. Applicant is given TWO MONTHS from the date of this Notice within which to correct the informalities indicated below. Extensions of time may be obtained by filing a petition accompanied by the extension fee under the provisions of 37 CFR 1.136(a).

The required item(s) identified below must be timely submitted to avoid abandonment:

- Replacement drawings in compliance with 37 CFR 1.84 and 37 CFR 1.121 are required. The drawings submitted are not acceptable because:
 - The drawings have a line quality that is too light to be reproduced (weight of all lines and letters must be heavy enough to permit adequate reproduction) or text that is illegible (reference characters, sheet numbers, and view numbers must be plain and legible) see 37 CFR 1.84(l) and (p)(1)); See Figure(s) 3.

Replies should be mailed to: Mail Stop Missing Parts
Commissioner for Patents
P.O. Box 1450
Alexandria VA 22313-1450

*A copy of this notice **MUST** be returned with the reply.*

Customer Service Center
Initial Patent Examination Division (703) 308-1202

PART 2 - COPY TO BE RETURNED WITH RESPONSE